EQUIPMENT SAFETY RECALL QUARTERLY REPORT INFORMATION¹

Required per 49 CFR Part 573.6

Report Date: January 30, 2015 Calendar Quarter: 4th Quarter 2014

Safety Recall Quarterly Report from October 1, 2014 through December 31, 2014

Manufacturer: Extang Corporation ("Extang")

Report Author: Steve Kelley Phone: (734) 434-3516

VP - Sales

Recall Subject: Aftermarket Truck Bed Cover

1. NHTSA Safety Recall Campaign Number: **13E-066**Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: **None**

2. (a) The date notification to purchasers began: Distributors & E-tailers 12/6/2013

Retail Outlets & Jobbers 01/21/2014 Consumers 01/21/2014

(b) The date notification to purchasers was completed: **Notification continues as Extang** receives additional vehicle owner information from its distributors and jobbers:

4,966 Owners Identified

969 Owners Responded and Claim in Process

41 Owner Information Outstanding²

8,726 Owner Information Unavailable At This Time³

3. The Total Number of Items of Equipment Involved: 14,204

Number of Items Returned from Inventory or Remedied Prior to Sale: 467

4. (a) Total Number Inspected & Remedied: 1,930 Remedied

587 Remedy in Process⁴

¹ This report is being submitted to the recall portal for 13E-066, which contains additional information about the recall remedy program being administered by Extang Corporation.

² Includes owner records sent by jobbers that only contain the owner's name and no contact information.

³ Includes owner records that jobbers report are unavailable and also owner records attributed to sales to jobbers that have either not yet responded to requests for owner information or are believed to no longer be in business.

- (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
- 5. Items Determined to be Unreachable:

Total Number Exported: 4
Total Number Stolen: 0
Total Number Scrapped: 0

Total Number Unable to Notify: 8,726 -- Owner Information Unavailable At

This Time

Total Number Otherwise Unreachable: 0

Describe Other:

- 3,344 Owner Letters Mailed (1st mailing)
- 1,613 Owners contacted by phone, which was the only contact information that was available for these owners.
- 9 owners contacted by email, which was the only contact information that was available for these owners.
- 1,153 owners contacted two (2) times by using one or a combination of the following communication methods (mail, phone, email)
- 673 owners contacted three (3) times by using one or a combination of the following communication methods (mail, phone, email)
- 198 owners contacted four (4) times by using one or a combination of the following communication methods (mail, phone, email)
- 338 owners contacted five (5) times by using one or a combination of the following communication methods (mail, phone, email)
- 935 owners contacted six (6) times by using one or a combination of the following communication methods (mail, phone, email)
- 324 owners contacted six (7) times by using one or a combination of the following communication methods (mail, phone, email)

⁴ Repair kits shipped to assigned dealer for installations.